


## Monitoring and Totalizing Flow

## **PROBLEM**

Add a totalizer to a process flow monitoring system.

## **SOLUTION**

An **API 7500 G M02** Field Selectable Isolated DC to Frequency Transmitter module is inserted in the 4-20 mA loop between the turbine flow meter and the chart recorder.



The API 7500 G M02 provides the 9 V p-p square wave required by the totalizer system.

## Did You Know...?

That Api has field selectable units to convert frequency to voltage (API 7580 G) and voltage to frequency (API 7500 G).



Rev 04/02 APIAN331 F-9